


MERCEDES GLB: 1YXW324

Vinnnumber:	W1N2476101W087414	Versionname:	GLB GLB 180 d Business Solution 85kW/116pk
First Registrationdate:	26/01/2021	Fiscalpower:	5D/P Auto-8
Expertise Mileage:	133749	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b213
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
GPS storage	HD	Sun Roof electric	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 55 / 18 / 100 / W / Aluminium	4,0 mm	Pirelli	Summer
	Right	235 / 55 / 18 / 100 / W / Aluminium	4,0 mm	Pirelli	Summer
Rear	Left	235 / 55 / 18 / 100 / W / Aluminium	5,0 mm	Pirelli	Summer
	Right	235 / 55 / 18 / 100 / W / Aluminium	4,0 mm	Pirelli	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable




Steering wheel, Worn, Acceptable




Interior, Dirty, Chemical cleaning




Bonnet, Dent(s), Acceptable



Bumper F, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Acceptable




Step L, Dent(s) and scratch(es), Spot repair



Door FL, Dent(s) and scratch(es), Spot repair



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Rear light R, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Polish



Door FR, Dent(s) and scratch(es), Spot repair




Door RR, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Repair and paint (complete)




Wing RR, Dent(s), Acceptable



Panoramic roof, Scratch(es), Polish



Roof, Chemical pollution, Polish



Bodywork, No damage, Acceptable

