



**VOLVO V60: 2BGY037**

Vinnumber:	<b>YV1ZWBFVDN1481369</b>	Versionname:	<b>V60 T6 Recharge 4x4 Geartr. Inscription Expr (PHEV) 251kW/341pk 5D/P Auto-8</b>
First Registrationdate:	<b>22/11/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>81546</b>	Power Kw:	
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>a112</b>
Fueltype:	<b>Hybrid Petrol</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio	
Number keys remote:	<b>2</b>	Lining leather	
Windows electric F:		Front parking sensors	
Windows electric R:		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

**Limited Technical Inspection**

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Transmission:	<b>OK</b>

**Tyres**

235/45/18/98 V				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL	4.0			
Tyre profile depth FR	4.0			
Tyre profile depth RL	4.0			
Tyre profile depth RR	4.0			
Tyre size FL	235/45 R 18 98 V			
Tyre size FR	235/45 R 18 98 V			
Tyre size RL	235/45 R 18 98 V			
Tyre size RR	235/45 R 18 98 V			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	256			
Tyre make FR	256			
Tyre make RL	256			
Tyre make RR	256			

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>1</b>		
Number of charging cables (rapid charge):	<b>1</b>		

Interior, Smell, Ozone treatment



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish




Steel rim RL, Scratch(es), Repair and paint (complete)




Door FL, Dent(s) and scratch(es), Spot repair



Door RL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Rear spoiler, Dent(s), Repair and paint (complete)



Reflector, Scratch(es), Polish




Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Rear light L, Scratch(es), Polish




Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Polish



Mirror side repeater R, Scratch(es), Polish



Door RR, Scratch(es), Acceptable



Wing RR, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

