



VOLVO EX30: 2GKZ217

Vinnnumber:	YV12ZEK92SS133190	Versionname:	EX30 Twin Motor Performance Ultra 315kW/428pk
First Registrationdate:	15/01/2025	Fiscalpower:	5D/P Auto-1 - WLTP onvolledig
Expertise Mileage:	23349	Power Kw:	315
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	4 Wheel-drive	Parking lot:	c215
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	3	Radio
Number keys remote:	0	Front parking sensors
Windows electric F:		Rear parking sensors
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Seats F heated:		
Navigation with screen:		
Airco electronic:		
Rims alloy:		

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

245/45/19/102 V				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				245/45 R 19 102 V
Tyre size FR				245/45 R 19 102 V
Tyre size RL				245/45 R 19 102 V
Tyre size RR				245/45 R 19 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	1		


Instrument panel, complete, Repaired, Acceptable



Bumper F, Scratch(es), Polish




Bonnet, Scratch(es), Polish



Roof pillar L, Dent(s), Acceptable




Wing RL, Scratch(es), Acceptable



Charging cable (normal), Missing, Replace



Door RR, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

