



MERCEDES A-Klasse: 2BHL723				
Vinnumber:	W1K1770841V118204	Versionname:	A-Klasse A 180 Business Solution 100kW/136pk 5D/P Man-6	
First Registrationdate:	26/11/2021	Fiscalpower:		
Expertise Mileage:	39751	Power Kw:		
Bodytype:		Body colour	Black	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium	
Transmission:	Front	Parking lot	b112	
Fueltype:	Petrol			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Bodywork	Clean			
Interior	Clean			
Options				
Number of keys total	2	Radio		
Number keys remote	2	Front parking sensors		
GPS storage	HD	Rear parking sensors		
Windows electric F				
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Seats F heated				
Alarm				
Navigation with screen				
Airco electronic				
Rims alloy				
Limited Technical Inspection				
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Transmission	OK	
Tyres				
	205/60/16/96 H			
Winter tyres:	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 5 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2485
Tyre make FR				2485
Tyre make RL				258
Tyre make RR				258
Assistance equipment				
Repair kit	Yes	Compressor		Yes

Number of charging cables (normal)
Number of charging cables (rapid charge)

0
0

Gear shift lever knob, Worn, Acceptable



Instrument panel, complete, Not functioning (well), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Headlight R, Scratch(es), Replace




Engine insulation, Missing, Replace



Door RL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Luggage compartment cover, Broken, Replace



Bumper R, Scratch(es), Polish



Rear window, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

