



PEUGEOT 2008: 2BFP224			
Vinnnumber:	VR3USHNKKMJ832341	Versionname:	2008 1.2 Puretech S/S Allure Pack 74kW/100pk
First Registrationdate:	4/11/2021	Fiscalpower:	5D/P Man-6
Expertise Mileage:	41588	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	b323
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options	
Number of keys total	2
Number keys remote	2
Windows electric F	Radio
Windows electric R	Rear parking sensors
Cruise Control	Fog lights (front)
Steering wheel multifunctional	
Seats F heated	
Airco electronic	
Rims alloy	

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres			
Summer tyres:	215/50/17/96 H		
	Fr.L.	Michelin: 3 mm	Fr.R.
	Re.L.	Michelin: 3 mm	Re.R.
Tyre profile depth FL			3.0
Tyre profile depth FR			3.0
Tyre profile depth RL			3.0
Tyre profile depth RR			3.0
Tyre size FL			215/50 R 17 96 H
Tyre size FR			215/50 R 17 96 H
Tyre size RL			215/50 R 17 96 H
Tyre size RR			215/50 R 17 96 H
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			261
Tyre make FR			261
Tyre make RL			261
Tyre make RR			261

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Interior, Stain, Cleaning




Bonnet, Chemical polution, Polish



Alloy rim FL polished, Scratch(es), Repair and paint (complete)




Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Wing RL, Scratch(es), Acceptable



Wing FL, Scratch(es), Polish



Wing trim FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable




Rear light L, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing trim FR, Scratch(es), Acceptable



Wing FR, Repaired, Acceptable



Door FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

