



PEUGEOT 2008: 2BJL709				
Vinnumber:	VR3USHNSSMJ905485	Versionname:	2008 1.2 Puretech S/S EAT8 GT 96kW/130pk 5D/P Auto-8	
First Registrationdate:	8/12/2021	Fiscalpower:		
Expertise Mileage:	38818	Power Kw:		
Bodytype:		Body colour	White	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:	Front	Parking lot	pp92	
Fueltype:	Petrol			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Bodywork	Clean			
Interior	Clean			
Options				
Number of keys total	2	Radio		
Number keys remote	2	Front parking sensors		
GPS storage	HD	Rear parking sensors		
Windows electric F		Fog lights (front)		
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Navigation with screen				
Airco electronic				
Rims alloy				
Limited Technical Inspection				
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Transmission	OK	
Tyres				
Winter tyres:	215/60/17/96 H			
	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				215/60 R 17 96 H
Tyre size FR				215/60 R 17 96 H
Tyre size RL				215/60 R 17 96 H
Tyre size RR				215/60 R 17 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				2484
Tyre make RR				2484
Assistance equipment				
Spare wheel	Yes			
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			

Instrument panel, complete, Not functioning (well), Acceptable



Bumper F, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Engine insulation, Hole, Replace



Step L, Scratch(es), Acceptable



Tailgate / Boot, Repaired, Acceptable



Bumper R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable




Alloy rim RR polished, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable






Door FR, Repaired, Acceptable



Wing RR, Repaired, Acceptable



Roof, Dent(s), Acceptable



Bodywork, No damage, Acceptable

