



**MERCEDES CLA: 2ASB737**

Vinnumber:	<b>W1K1183841N237607</b>	Versionname:	<b>CLA CLA 180 Business Solution 100kW/136pk 4D/P Man-6</b>
First Registrationdate:	<b>28/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>99361</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>d024</b>
Fueltype:	<b>Petrol</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total	<b>2</b>	Radio	
Number keys remote	<b>2</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

**Limited Technical Inspection**

Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Transmission	<b>OK</b>

**Tyres**

<b>205/55/17/95 V</b>				
Winter tyres:	Fr.L.	<b>Dunlop: 4 mm</b>	Fr.R.	<b>Dunlop: 4 mm</b>
	Re.L.	<b>Dunlop: 4 mm</b>	Re.R.	<b>Dunlop: 4 mm</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>205/55 R 17 95 V</b>
Tyre size FR				<b>205/55 R 17 95 V</b>
Tyre size RL				<b>205/55 R 17 95 V</b>
Tyre size RR				<b>205/55 R 17 95 V</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>257</b>
Tyre make FR				<b>257</b>
Tyre make RL				<b>257</b>
Tyre make RR				<b>257</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		

Instrument panel, complete, Repaired, Acceptable



Door panel RL, Scratch(es), Acceptable



Seat cover FR, Repaired, Acceptable



Bumper F, Scratch(es), Spot repair




Brand badge F, Broken, Replace




Windscreen, Repaired, Acceptable



Bonnet, Stone chip(s), Acceptable




Door FL, Scratch(es), Acceptable



Central pillar L, Dent(s), Acceptable



Door RL, Repaired, Acceptable



Step L, Dent(s), Acceptable



Wing RL, Scratch(es), Acceptable




Door seal RL, Broken, Replace



Bumper R, Dent(s), Acceptable



Bumper moulding R, Broken, Replace



Tailgate / Boot, Dent(s), Spot repair



Bumper trim R, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Central pillar R, Dent(s) and scratch(es), Spot repair



Door FR, Dent(s), Acceptable



Step R, Dent(s) and scratch(es), Spot repair



Door RR, Dent(s), Acceptable



Wing RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

