



PEUGEOT 2008: 2BGB224

Vinnnummer:	VR3UKZKXZMJ872409	Versionname:	2008 e-2008 GT 100kW/136pk 5D/P Auto-1
First Registrationdate:	10/11/2021	Fiscalpower:	
Expertise Mileage:	38505	Power Kw:	
Bodytype:		Body colour:	Red
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	B119
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Dirty		

Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
GPS storage		Sun Roof electric
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Airco functioning	Yes	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Transmission	OK
Exhaust gass	OK		

Degree of wear

215/60/17/96 H			
Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Winter tyres:			
Tyre profile depth FL			7.0
Tyre profile depth FR			7.0
Tyre profile depth RL			7.0
Tyre profile depth RR			7.0
Tyre size FL			215/60 R 17 96 H
Tyre size FR			215/60 R 17 96 H
Tyre size RL			215/60 R 17 100 V
Tyre size RR			215/60 R 17 100 V
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			2484
Tyre make FR			2484
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Bumper spoiler F, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Tailgate / Boot, Not original part, Acceptable



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)

