



MERCEDES Sprinter: 1WVV973				
Vinnumber:	WDB9106331P133346	Versionname:	Sprinter 311 CDI GB L2 FWD Functional 3.5T	
First Registrationdate:	1/10/2019	Fiscalpower:	84kW/114pk 4D/P Man-6	
Expertise Mileage:	15612	Power Kw:		
Bodytype:		Body colour	Blue	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel	
Transmission:	Front	Parking lot	d141	
Fueltype:	Diesel			
Number of doors	5			
Number of seats	3			
Number head rests	3			
Type of rims (mounted)	Steel			
Certificate of Conformity	Yes			
Category	Light Commercial Vehicle			
Registration Certificate Car (BE)	Yes			
Bodywork	Dirty			
Interior	Clean			
Options				
Number of keys total	2	Radio		
Number keys remote	2			
Windows electric F				
Steering wheel multifunctional				
Airco electronic				
Limited Technical Inspection				
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Transmission	OK	
Tyres				
	225/65/16/110 R			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/65 R 16 110 R
Tyre size FR				225/65 R 16 110 R
Tyre size RL				225/65 R 16 110 R
Tyre size RR				225/65 R 16 110 R
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Instrument panel, complete, Not functioning (well), Acceptable				



Instrument panel, complete, Not functioning (well), Check



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s), Acceptable



Central pillar L, Dent(s) and scratch(es), Spot repair



Wheel arch cover FL, Broken, Replace



Partition wall, Dent(s), Acceptable



Wheel aperture RL, Dent(s) and scratch(es), Acceptable



Wheel aperture RR, Dent(s) and scratch(es), Acceptable



Boot door panel RL, Dent(s), Paintless dent repair



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)




Rear light R, Scratch(es), Polish



Bumper moulding R, Scratch(es), Replace



Bumper R, Scratch(es), Smart repair



Bumper moulding R, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Door FR, Dent(s), Acceptable



Central pillar R, Dent(s), Acceptable



Sliding door R, Scratch(es), Spot repair





Door trim RR, Scratch(es), Replace



Wing RR, Rust, Spot repair



Wing trim RR, Missing, Replace



Wheel arch cover FR, Broken, Replace



Wing trim RR, Scratch(es), Replace



Bodywork, Not original part, Remove lettering



Bodywork, No damage, Acceptable



Bodywork, No damage, Acceptable

