


MERCEDES CLA Shooting Brake: 2CMS892

Vinnnumber:	W1K5M8GB6PN342510	Versionname:	CLA Shooting Brake CLA 250 e Business Solution (PHEV) 160kW/218pk 5D/P Auto-8
First Registrationdate:	19/09/2022	Fiscalpower:	
Expertise Mileage:	111386	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b418
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio	
Number keys remote:	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 17 / 95 / V / Aluminium	3,0 mm	Continental	Summer
	Right	205 / 55 / 17 / 95 / V / Aluminium	3,0 mm	Continental	Summer
Rear	Left	205 / 55 / 17 / 95 / V / Aluminium	5,0 mm	Continental	Summer
	Right	205 / 55 / 17 / 95 / V / Aluminium	5,0 mm	Continental	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Instrument panel, complete, Repaired, Acceptable

Bumper F, Scratch(es), Spot repair




Bumper moulding F, Crack, Replace




Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door FL, Dent(s), Paintless dent repair




Alloy rim RL polished, Scratch(es), Polish




Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Spot repair



Bumper trim R, Crack, Replace





Bumper moulding R, Scratch(es), Replace



Rear light R tailgate, Waterinfiltration, Replace



Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Door FR, Dent(s) and scratch(es), Spot repair



Wing RR, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

