



VOLVO XC40: 2FCT799

Vinnumber:	YV1XZEHR0R2270622	Versionname:	XC40 Recharge Extended Range Ultimate
First Registrationdate:	26/03/2024		185kW/252pk 5D/P Auto-1 (4 seizoenen Banden) -
Expertise Mileage:	50644		WLTP indicatief
Bodytype:		Fiscalpower:	
Gearbox:	Automatic	Power Kw:	185
Transmission:	Back	Body colour:	Grey
Fueltype:	Electric	Type of rims (mounted):	Aluminium
Number of doors:	5	Parking lot:	pp19
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio	
Number keys remote:	2	Sun Roof electric	
Windows electric F:		Front parking sensors	
Windows electric R:		Rear parking sensors	
Cruise Control:		Fog lights (front)	
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

235/45/20/100 H				
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 2 mm
	Re.L.	Pirelli: 2 mm	Re.R.	Pirelli: 2 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				2.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				235/45 R 20 100 H
Tyre size FR				235/45 R 20 100 H
Tyre size RL				255/40 R 20 101 H
Tyre size RR				255/40 R 20 101 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		


Instrument panel, complete, Not functioning (well), Acceptable



Interior covering A pillar R, Scratch(es), Acceptable



Bonnet, Chemical polution, Polish



Windscreen, Stone chip(s), Windscreen repair



Outside rear-view mirror housing L, Scratch(es), Polish



Mirror side repeater L, Scratch(es), Polish



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Polish



Rear light L, Scratch(es), Polish



Rear spoiler, Scratch(es), Acceptable



Door FR, Repaired, Acceptable




Door RR, Repaired, Acceptable



Bodywork, No damage, Acceptable



Panoramic roof, Scratch(es), Polish



Roof, Scratch(es), Acceptable

