



OPEL Corsa: 2DEW145			
Vinnumber:	VXKUPHNSSN4451045	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk
First Registrationdate:	27/02/2023	Fiscalpower:	5D/P Auto-8
Expertise Mileage:	13395	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	PP15
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options			
Number of keys total	2	Front parking sensors	
Number keys remote	2	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Airco manual			
Rims alloy			

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres			
	195/55/16/91 V		
Summer tyres:	Fr.L.	Other: 7 mm	Fr.R.
	Re.L.	Goodyear: 6 mm	Re.R.
			Goodyear: 6 mm
Tyre profile depth FL			7.0
Tyre profile depth FR			7.0
Tyre profile depth RL			6.0
Tyre profile depth RR			6.0
Tyre size FL			195/55 R 16 91 V
Tyre size FR			195/55 R 16 91 V
Tyre size RL			195/55 R 16 91 H
Tyre size RR			195/55 R 16 91 H
Tyre type FL			All seasons
Tyre type FR			All Seasons
Tyre type RL			All seasons
Tyre type RR			All Seasons
Tyre make FL			263
Tyre make FR			263
Tyre make RL			259
Tyre make RR			259

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Stain, Cleaning



Seat cover R, Stain, Cleaning



Bonnet, Dent(s), Paintless dent repair



Central pillar L, Bad repair, Spot repair



Boot lid covering R, Scratch(es), Acceptable



Rear spoiler, Bad repair, Spot repair



Bumper R, Bad repair, Spot repair



Door FR, Bad repair, Spot repair



Wing FR, Bad repair, Spot repair

