



PEUGEOT 2008: 2BEP207

Vinnumber:	VR3USHNSKMJ830393	Versionname:	2008 1.2 Puretech S/S Allure 96kW/130pk 5D/P
First Registrationdate:	22/10/2021	Fiscalpower:	Man-6
Expertise Mileage:	39211	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	a120
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

215/60/17/96 H				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				215/60 R 17 96 H
Tyre size FR				215/60 R 17 96 H
Tyre size RL				215/60 R 17 96 H
Tyre size RR				215/60 R 17 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Not functioning (well), Acceptable



Instrument panel, complete, Not functioning (well), Check



Bumper F, Scratch(es), Acceptable



Bumper spoiler F, Scratch(es), Acceptable



Bonnet, Dent(s), Paintless dent repair



Wing trim RL, Scratch(es), Acceptable




Bumper moulding R, Scratch(es), Acceptable




Rear window, Scratch(es), Polish



Wing RR, Repaired, Acceptable



Door RR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

