



### PEUGEOT 208: 2BSX431

Vinnnummer:	<b>VR3UPHNSSMT121074</b>	Versionname:	<b>208 1.2 PureTech 130 EAT8 S/S Allure pack</b>
First Registrationdate:	<b>10/03/2022</b>	Fiscalpower:	<b>96kW/130pk 5D/P Auto-8</b>
Expertise Mileage:	<b>86184</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>c508</b>
Fueltype:	<b>Petrol</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

### Options

Number of keys total	<b>2</b>	Radio
Number keys remote	<b>2</b>	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		
Rims alloy		

### Limited Technical Inspection

Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Transmission	<b>OK</b>

### Tyres

195/55/16/87 H				
Winter tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>3.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>195/55 R 16 87 H</b>
Tyre size FR				<b>195/55 R 16 87 H</b>
Tyre size RL				<b>195/55 R 16 87 H</b>
Tyre size RR				<b>195/55 R 16 87 H</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>261</b>
Tyre make FR				<b>261</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

### Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Instrument panel, complete, Repaired, Acceptable




Bonnet, Stone chip(s), Acceptable



Wing FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Paintless dent repair



Step L, Dent(s), Acceptable



Wheel aperture RL, Dent(s), Paintless dent repair




Rear window, Scratch(es), Polish





Bumper R, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Door FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Dent(s), Acceptable

