



MERCEDES CLA: 2BEE091

Vinnumber:	W1K1183861N255812	Versionname:	CLA CLA 250 e Business Solution 160kW/218pk 4D/P Auto-8
First Registrationdate:	19/10/2021	Fiscalpower:	
Expertise Mileage:	65821	Power Kw:	
Bodytype:		Body colour:	White
Gearbox:	Automatic	Parking lot:	c112
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol		
Number of seats:	5		
Bodywork:	Clean		
Registration Certificate Car (BE):	Yes		
Number of doors:	4		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Interior:	Clean		

Options

Alarm		Front parking sensors	
Rims alloy		Lining leather	
Number of keys total	1	Radio	
Windows electric F		Rear parking sensors	
Airco electronic		Sun Roof electric	
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Number keys remote	1		
Windows electric R			
Cruise Control			

Limited Technical Inspection

Engine startingtime	OK	Sound engine	OK
Idle position	OK	Transmission	OK
Exhaust gass	OK	Clutch test	OK

Tyres

205/55/17/95 V				
Winter tyres:	Fr.L.	Semperit: 3 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm
Tyre size RR	205/55 R 17 95 V			
Tyre make RR	2480			
Tyre profile depth FL	3.0			
Tyre type FR	Winter			
Tyre size FL	205/55 R 17 95 V			
Tyre make FL	2477			
Tyre profile depth RL	3.0			
Tyre make RL	2480			
Tyre type RR	Winter			
Tyre size RL	205/55 R 17 95 V			
Tyre type FL	Winter			
Tyre type RL	Winter			
Tyre profile depth FR	3.0			
Tyre make FR	2477			
Tyre profile depth RR	3.0			
Tyre size FR	205/55 R 17 95 V			




Assistance equipment

Number of charging cables (rapid charge)	1	Compressor	Yes
Repair kit	Yes		

Ignition key, Missing, Replace




Bumper F, Scratch(es), Spot repair




Windscreen, Crack, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Side window trim FL, Scratch(es), Acceptable



Central pillar L, Dent(s), Acceptable



Door FL, Scratch(es), Acceptable




Step L, Dent(s), Acceptable





Alloy rim RL polished, Scratch(es), Acceptable




Tailgate / Boot, Chemical polution, Polish



Alloy rim FR polished, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

