

**SEAT Leon: 2CDG561**

Vinnumber:	VSSZZZKLZNR055709	Versionname:	Leon 1.0 eTSI 110 Move! DSG (Mild Hybrid)
First Registrationdate:	13/06/2022	Fiscalpower:	81kW/110pk 5D/P Auto-7
Expertise Mileage:	110413	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	d236
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Fog lights (front)	
Cruise Control			
Steering wheel multifunctional			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 16 / 94 / V / Aluminium	3,0 mm	Goodyear	Winter
	Right	205 / 55 / 16 / 94 / V / Aluminium	3,0 mm	Goodyear	Winter
Rear	Left	205 / 55 / 16 / 94 / V / Aluminium	6,0 mm	Goodyear	Winter
	Right	205 / 55 / 16 / 94 / V / Aluminium	6,0 mm	Goodyear	Winter

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable



Steering wheel, Worn, Acceptable



Bumper F, Scratch(es), Spot repair



Door RL, Scratch(es), Acceptable



Door window RL, Scratch(es), Polish




Alloy rim RL, Scratch(es), Repair and paint (complete)



Luggage compartment cover, Tear, Smart repair



Tailgate / Boot, Scratch(es), Polish



Rear window, Scratch(es), Polish



Bumper R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Wing RR, Scratch(es), Spot repair



Bodywork, No damage, Acceptable



Roof, Scratch(es), Polish

