



SKODA Octavia Combi: 2CCW493

Vinnumber:	TMBJP7NX8NY105165	Versionname:	Octavia Combi 1.0 TSI Clever 81kW/110pk 5D/P Man-6
First Registrationdate:	8/06/2022	Fiscalpower:	
Expertise Mileage:	166775	Power Kw:	
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c216
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	1	Radio	
Number keys remote	1	Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Fog lights (front)	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 96 / V / Aluminium	4,0 mm	Fulda	Summer
	Right	205 / 60 / 16 / 96 / V / Aluminium	4,0 mm	Fulda	Summer
Rear	Left	205 / 60 / 16 / 96 / V / Aluminium	4,0 mm	Kumho	Summer
	Right	205 / 60 / 16 / 96 / V / Aluminium	4,0 mm	Kumho	Summer


Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Ignition key, Missing, Replace



Instrument panel, complete, Repaired, Acceptable



Floor covering FL, Hole, Replace



Interior, Stain, Cleaning




Interior, Smell, Ozone treatment




Windscreen, Stone chip(s), Windscreen repair



Bonnet, Dent(s) and scratch(es), Spot repair



Bumper F, Dent(s) and scratch(es), Spot repair




Bumper moulding F, Scratch(es), Replace



Wing RL, Dent(s), Spot repair



Step L, Dent(s) and scratch(es), Spot repair



Door RL, Scratch(es), Polish



Door FL, Dent(s) and scratch(es), Spot repair



Outside rear-view mirror housing L, Scratch(es), Acceptable



Wing FL, Chemical polution, Polish



Luggage compartment cover, Missing, Replace




Boot lid covering R, Scratch(es), Acceptable



Bumper R, Bad repair, Repair and paint (complete)






Reflector, Broken, Replace



Tailgate / Boot, Scratch(es), Polish




Rear light R, Scratch(es), Polish




Alloy rim FR, Scratch(es), Acceptable




Wing FR, Chemical polution, Polish




Door FR, Chemical polution, Polish



Door RR, Scratch(es), Polish



Wing RR, Dent(s), Spot repair



Bodywork, No damage, Acceptable

