


MERCEDES GLC: 2BQK903

Vinnumber:	W1N2539131V348273	Versionname:	GLC GLC 200 d Business Solution 120kW/163pk 5D/P Auto-9
First Registrationdate:	15/02/2022	Fiscalpower:	
Expertise Mileage:	109116	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c118
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 55 / 19 / 101 / V / Aluminium	6,0 mm	Bridgestone	Summer
	Right	235 / 55 / 19 / 101 / V / Aluminium	6,0 mm	Bridgestone	Summer
Rear	Left	235 / 55 / 19 / 101 / V / Aluminium	6,0 mm	Bridgestone	Summer
	Right	235 / 55 / 19 / 101 / V / Aluminium	6,0 mm	Bridgestone	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable




Backrest cover FL, Hole, Smart repair



Bumper F, Scratch(es), Polish




Bonnet, Scratch(es), Polish




Mirror side repeater L, Scratch(es), Polish




Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Outside rear-view mirror base L, Scratch(es), Smart repair




Door FL, Scratch(es), Acceptable




Step L, Dent(s) and scratch(es), Spot repair



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Rear light R, Scratch(es), Polish




Alloy rim FR, Scratch(es), Polish



Mirror side repeater R, Crack, Replace



Wing RR, Dent(s), Paintless dent repair



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable

