



OPEL Corsa: 2BCN025

Vinnnumber:	VXKUPHNEKM4310736	Versionname:	Corsa 1.2 Turbo S/S GS Line 74kW/100pk 5D/P
First Registrationdate:	30/09/2021	Fiscalpower:	Man-6
Expertise Mileage:	44641	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c612
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Fog lights (front)	
Cruise Control			
Steering wheel multifunctional			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

235/40/19/96 Y				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				3
Tyre profile depth FR				3
Tyre profile depth RL				3
Tyre profile depth RR				3
Tyre size FL				235/40 R 19 96
Tyre size FR				235/40 R 19 96
Tyre size RL				235/40 R 19 96
Tyre size RR				205/45 R 17 88
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Door panel RL, Scratch(es), Acceptable



Engine insulation, Missing, Replace




Bumper F, Scratch(es), Acceptable



Bonnet, Chemical polution, Polish



Wing FL, Dent(s), Spot repair



Alloy rim FL, Scratch(es), Acceptable



Door FL, Dent(s), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable




Outer door handle FL, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Spot repair




Alloy rim FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Door RR, Dent(s), Paintless dent repair



Alloy rim RR, Scratch(es), Acceptable



Wing RR, Dent(s), Spot repair



Bodywork, No damage, Acceptable

