



PEUGEOT 2008: 2BQV244

Vinnnumber:	VR3USHNKKMJ906586	Versionname:	2008 1.2 Puretech S/S Active 74kW/100pk 5D/P Man-6
First Registrationdate:	18/02/2022	Fiscalpower:	
Expertise Mileage:	43028	Power Kw:	
Bodytype:		Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c311
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	1	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

215/65/16/98 H				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/65 R 16 98 H
Tyre size FR				215/65 R 16 98 H
Tyre size RL				215/65 R 16 98 H
Tyre size RR				215/65 R 16 98 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FR, Stain, Cleaning



Seat cover R, Stain, Cleaning



Instrument panel, complete, Repaired, Acceptable



Bumper F, Stone chip(s), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Windscreen, Stone chip(s), Acceptable



Wing FL, Scratch(es), Acceptable



Wheel cover RL, Scratch(es), Replace



Door seal FL, Deformed / Strained, Replace




Wing trim FL, Scratch(es), Acceptable







Roof pillar L, Scratch(es), Polish




Boot lid covering R, Scratch(es), Acceptable




Tailgate / Boot, Dent(s), Paintless dent repair



Bumper trim R, Dent(s) and scratch(es), Replace



Bumper moulding R, Scratch(es), Acceptable



Rear light L, Scratch(es), Polish



Bodywork, No damage, Acceptable

