


OPEL Corsa: 2CNN016

Vinnnumber:	VXKUPHNSSN4346483	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk
First Registrationdate:	28/09/2022	Fiscalpower:	5D/P Auto-8
Expertise Mileage:	20074	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c628
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio
Number keys remote:	2	Front parking sensors
Windows electric F:		Rear parking sensors
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Seats F heated:		
Airco manual:		
Rims alloy:		

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

195/55/16/91 V				
Summer tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/55 R 16 91 V
Tyre size FR				195/55 R 16 91 V
Tyre size RL				195/55 R 16 91 V
Tyre size RR				195/55 R 16 91 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Seat cover FL, Not original part, Repair/replace (lump sum)




Door panel FL, Bad repair, Check



Engine insulation, Missing, Replace



Bonnet, Scratch(es), Acceptable



Door FL, Dent(s), Paintless dent repair



Boot lid covering R, Scratch(es), Smart repair



Bodywork, No damage, Acceptable



Bodywork, Missing, Replace

