



MERCEDES EQA: 2BGH182

Vinnumber:	W1N2437011J021029	Versionname:	EQA EQA 250 Business Solution Luxury
First Registrationdate:	15/11/2021	Fiscalpower:	140kW/190pk 5D/P Auto-1
Expertise Mileage:	63752	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	a322
Fueltype:	Electric		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

235/55/18/104 V			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Bridgestone: 5 mm	Re.R.

Tyre profile depth FL	4.0
Tyre profile depth FR	4.0
Tyre profile depth RL	5.0
Tyre profile depth RR	5.0
Tyre size FL	235/55 R 18 104 V
Tyre size FR	235/55 R 18 104 V
Tyre size RL	235/55 R 18 104 V
Tyre size RR	235/55 R 18 104 V
Tyre type FL	Summer
Tyre type FR	Summer
Tyre type RL	All seasons
Tyre type RR	All Seasons
Tyre make FL	256
Tyre make FR	256
Tyre make RL	255
Tyre make RR	255

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

1

1

Bonnet, Scratch(es), Polish



Bumper moulding F, Scratch(es), Acceptable



Headlight R, Waterinfiltration, Acceptable




Door RL, Dent(s) and scratch(es), Spot repair



Door FL, Dent(s), Acceptable




Mirror side repeater L, Scratch(es), Acceptable



Wing FL, Repaired, Acceptable



Tailgate / Boot, Dent(s), Paintless dent repair





Rear light R, Scratch(es), Polish




Bumper R, Scratch(es), Polish



Door FR, Dent(s), Acceptable



Wing RR, Dent(s), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

