



HYUNDAI Tucson: 1YAU365

Vinnumber:	TMAJ3817HLJ109991	Versionname:	Tucson 1.6 CRDi ISG Shine 4WD DCT-7
First Registrationdate:	2/07/2020	Fiscalpower:	100kW/136pk 5D/P Auto-7
Expertise Mileage:	89237	Power Kw:	100
Bodytype:	Automatic	Body colour:	Grey
Gearbox:	Front	Type of rims (mounted):	Aluminium
Transmission:	Diesel	Parking lot:	a202
Fueltype:	5		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Sun Roof electric	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Fog lights (front)	
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK


Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / Y / Aluminium	5,0 mm	Hankook	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	5,0 mm	Hankook	Summer
Rear	Left	245 / 45 / 19 / 102 / Y / Aluminium	4,0 mm	Continental	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	4,0 mm	Continental	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Backrest cover FL, Worn, Acceptable





Door panel RL, Worn, Acceptable



Instrument panel, complete, Repaired, Acceptable




Door panel FL, Scratch(es), Acceptable



Door panel RR, Scratch(es), Acceptable




Bonnet, Dent(s), Paintless dent repair



Grille, Crack, Replace




Bumper spoiler F, Scratch(es), Smart repair



Alloy rim FL polished, Scratch(es), Repair and paint (complete)




Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Spot repair



Boot lid covering R, Scratch(es), Smart repair



Tailgate / Boot, Dent(s), Spot repair




Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Paintless dent repair



Bodywork, No damage, Acceptable

