


MERCEDES Sprinter: 2ATL350

Vinnumber:	W1V9076551P376752	Versionname:	Sprinter 516 CDI GB L3 RWD 7G-TRONIC 5.0T 120kW/163pk 4D/P Auto-7
First Registrationdate:	9/07/2021	Fiscalpower:	
Expertise Mileage:	117949	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Steel
Transmission:	Front	Parking lot	d153
Fueltype:	Diesel		
Number of doors	5		
Number of seats	2		
Number head rests	2		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Navigation with screen			
Airco electronic			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 75 / 16 / 111 / R / Steel	6,0 mm	Michelin	Summer
	Right	205 / 75 / 16 / 111 / R / Steel	6,0 mm	Michelin	Summer
Rear	Left	205 / 75 / 16 / 111 / R / Steel	4,0 mm	Continental	Summer
	Right	205 / 75 / 16 / 111 / R / Steel	4,0 mm	Continental	Summer

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable




Instrument panel, complete, Not functioning (well), Check




Bumper F, Scratch(es), Acceptable



Windscreen, Repaired, Acceptable



Wing RL, Dent(s), Paintless dent repair



Wing trim RL, Deformed / Strained, Acceptable



Mirror side repeater L, Deformed / Strained, Replace



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Replace



Reflector, Broken, Replace



Boot door panel RR, Dent(s) and scratch(es), Spot repair



Rear light R, Scratch(es), Polish



Rear light L, Scratch(es), Polish



Sliding door R, Scratch(es), Polish



Door trim RR, Scratch(es), Acceptable



Central pillar R, Dent(s) and scratch(es), Spot repair



Outer sill R, Crack, Replace and paint



Wing RR, Scratch(es), Polish



Bodywork, No damage, Acceptable



Bodywork, No damage, Acceptable

