



SKODA Octavia Combi: 2CJV820

Vinnnumber:	TMBJW8NX5PY006539	Versionname:	Octavia Combi 1.4 TSI PHEV DSG6 Clever (PHEV)
First Registrationdate:	17/08/2022	Fiscalpower:	150kW/204pk 5D/P Auto-6
Expertise Mileage:	164481	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c505
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	3	Radio	
Number keys remote:	3	Sun Roof electric	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Fog lights (front)	
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 17 / 95 / V / Aluminium	4,0 mm	Michelin	Summer
	Right	205 / 55 / 17 / 95 / V / Aluminium	5,0 mm	Michelin	Summer
Rear	Left	205 / 55 / 17 / 95 / V / Aluminium	4,0 mm	Continental	Summer
	Right	205 / 55 / 17 / 95 / V / Aluminium	5,0 mm	Continental	Summer

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Instrument panel, complete, Repaired, Acceptable



Bumper moulding F, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable




Bonnet, Dent(s), Acceptable



Outer sill L, Dent(s) and scratch(es), Spot repair



Wing RL, Dent(s), Paintless dent repair




Alloy rim RL, Scratch(es), Polish



Bumper R, Scratch(es), Spot repair



Wing RR, Dent(s), Paintless dent repair



Step R, Dent(s), Acceptable

