



SKODA Octavia Combi: 2CGV299

Vinnnumber:	TMBJR7NX4NY076712	Versionname:	Octavia Combi 1.5 TSI DSG7 Clever+ (Mild Hybrid)
First Registrationdate:	19/07/2022	Fiscalpower:	110kW/150pk 5D/P Auto-7
Expertise Mileage:	75301	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b611
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Dirty		

Options

Number of keys total:	3	Radio:	
Number keys remote:	3	Sun Roof electric:	
GPS storage:	HD	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:		Fog lights (front):	
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Alarm:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 17 / 91 / W / Aluminium	4,0 mm	Continental	Summer
	Right	205 / 55 / 17 / 91 / W / Aluminium	4,0 mm	Continental	Summer
Rear	Left	205 / 55 / 17 / 91 / V / Aluminium	4,0 mm	Goodyear	Summer
	Right	205 / 55 / 17 / 91 / V / Aluminium	4,0 mm	Goodyear	Summer

Assistance equipment

Spare wheel:	Yes
Number of charging cables (normal):	0
Number of charging cables (rapid charge):	0

Instrument panel, complete, Repaired, Acceptable





Interior, Stain, Cleaning



Bonnet, Dent(s) and scratch(es), Spot repair




Wing RL, Dent(s), Spot repair




Step L, Dent(s) and scratch(es), Spot repair




Door FL, Scratch(es), Acceptable



Wing FL, Scratch(es), Polish



Rear light R, Scratch(es), Polish



Rear light L, Scratch(es), Polish




Tailgate / Boot, Scratch(es), Polish




Bumper R, Dent(s) and scratch(es), Spot repair



Alloy rim FR, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Polish



Step R, Dent(s), Paintless dent repair




Door RR, Scratch(es), Polish



Wing RR, Scratch(es), Acceptable



Roof, Dent(s), Acceptable



Bodywork, No damage, Acceptable

