



OPEL Astra: 2DEZ542

Vinnnummer:	VXKF3DGXTP1001190	Versionname:	Astra 1.6 Turbo Hybrid GS (PHEV) 132kW/180pk
First Registrationdate:	27/02/2023	Fiscalpower:	5D/P Auto-8 - CO2 onvolledig
Expertise Mileage:	39969	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	d237
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:		Fog lights (front):	
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK


Tyres

225/45/17/94 H				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				225/45 R 17 94 H
Tyre size FR:				225/45 R 17 94 H
Tyre size RL:				225/45 R 17 94 H
Tyre size RR:				225/45 R 17 94 H
Tyre type FL:				Winter
Tyre type FR:				Winter
Tyre type RL:				Winter
Tyre type RR:				Winter
Tyre make FL:				261
Tyre make FR:				261
Tyre make RL:				261
Tyre make RR:				261


Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Instrument panel, complete, Repaired, Acceptable




Seat cover FL, Worn, Acceptable



Bumper F, Scratch(es), Spot repair



Bonnet, Stone chip(s), Acceptable




Door FL, Dent(s), Acceptable



Door RL, Dent(s), Acceptable



Wing RL, Scratch(es), Acceptable




Alloy rim RL, Scratch(es), Acceptable



Rear spoiler, Scratch(es), Acceptable




Bumper moulding R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Dent(s), Paintless dent repair

