



| MERCEDES EQC: 2BLU360             |                   |                        |                                            |
|-----------------------------------|-------------------|------------------------|--------------------------------------------|
| Vinnnumber:                       | W1K2938901F034375 | Versionname:           | EQC EQC 400 4MATIC 300kW/408pk 5D/P Auto-1 |
| First Registrationdate:           | 6/01/2022         | Fiscalpower:           |                                            |
| Expertise Mileage:                | 53739             | Power Kw:              |                                            |
| Bodytype:                         |                   | Body colour            | Blue                                       |
| Gearbox:                          | Automatic         | Type of rims (mounted) | Aluminium                                  |
| Transmission:                     | 4 Wheel-drive     | Parking lot            | b502                                       |
| Fueltype:                         | Electric          |                        |                                            |
| Number of doors                   | 5                 |                        |                                            |
| Number of seats                   | 5                 |                        |                                            |
| Number head rests                 | 5                 |                        |                                            |
| Type of rims (mounted)            | Aluminium         |                        |                                            |
| Certificate of Conformity         | Yes               |                        |                                            |
| Category                          | Passenger Car     |                        |                                            |
| Registration Certificate Car (BE) | Yes               |                        |                                            |
| Bodywork                          | Clean             |                        |                                            |
| Interior                          | Clean             |                        |                                            |

| Options                        |   |
|--------------------------------|---|
| Number of keys total           | 2 |
| Number keys remote             | 2 |
| Windows electric F             |   |
| Windows electric R             |   |
| Cruise Control                 |   |
| Steering wheel multifunctional |   |
| Seats F heated                 |   |
| Navigation with screen         |   |
| Airco electronic               |   |
| Rims alloy                     |   |
| Radio                          |   |
| Lining leather                 |   |
| Front parking sensors          |   |
| Rear parking sensors           |   |

| Limited Technical Inspection |    |              |    |
|------------------------------|----|--------------|----|
| Idle position                | OK | Sound engine | OK |
| Engine startingtime          | OK | Clutch test  | OK |
| Exhaust gass                 | OK | Transmission | OK |

| Tyres                 |                 |                   |       |                   |
|-----------------------|-----------------|-------------------|-------|-------------------|
| Winter tyres:         | 235/55/19/105 V |                   |       |                   |
|                       | Fr.L.           | Continental: 4 mm | Fr.R. | Continental: 4 mm |
|                       | Re.L.           | Dunlop: 4 mm      | Re.R. | Dunlop: 4 mm      |
| Tyre profile depth FL |                 |                   |       | 4.0               |
| Tyre profile depth FR |                 |                   |       | 4.0               |
| Tyre profile depth RL |                 |                   |       | 4.0               |
| Tyre profile depth RR |                 |                   |       | 4.0               |
| Tyre size FL          |                 |                   |       | 235/55 R 19 105 V |
| Tyre size FR          |                 |                   |       | 235/55 R 19 105 V |
| Tyre size RL          |                 |                   |       | 235/55 R 19 105 V |
| Tyre size RR          |                 |                   |       | 235/55 R 19 105 V |
| Tyre type FL          |                 |                   |       | Winter            |
| Tyre type FR          |                 |                   |       | Winter            |
| Tyre type RL          |                 |                   |       | Winter            |
| Tyre type RR          |                 |                   |       | Winter            |
| Tyre make FL          |                 |                   |       | 256               |
| Tyre make FR          |                 |                   |       | 256               |
| Tyre make RL          |                 |                   |       | 257               |
| Tyre make RR          |                 |                   |       | 257               |

| Assistance equipment                     |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 1   |            |     |
| Number of charging cables (rapid charge) | 1   |            |     |

Door panel FL, Worn, Acceptable



Instrument panel, complete, Not functioning (well), Acceptable




Centre console, Scratch(es), Acceptable



Windscreen moulding, Stone chip(s), Acceptable



Bonnet, Stone chip(s), Acceptable




Bumper F, Stone chip(s), Acceptable



Bonnet, Dent(s), Acceptable




Alloy rim FL polished, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Polish



Boot lid covering R, Scratch(es), Replace



Internal boot lining L, Broken, Smart repair



Rear light L, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Wing RR, Dent(s), Acceptable



Door FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

