

## PEUGEOT 508: 2BMX913

Vinnumber:	<b>VR3FPHNSTMY540920</b>	Versionname:	<b>508 1.2 PureTech 130 S/S EAT8 GT 96kW/130pk 5D/P Auto-8</b>
First Registrationdate:	<b>19/01/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>41693</b>	Power Kw:	<b>96</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>b120</b>
Fueltype:	<b>Petrol</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Type of rims (mounted)	<b>Aluminium</b>		
Certificate of Conformity	<b>Yes</b>		
Category	<b>Passenger Car</b>		
Registration Certificate Car (BE)	<b>Yes</b>		
Bodywork	<b>Clean</b>		
Interior	<b>Clean</b>		

## Options

Number of keys total	<b>2</b>	Radio
Number keys remote		
Windows electric F	<b>2</b>	Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		
Rims alloy		

## Limited Technical Inspection

Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Transmission	<b>OK</b>

## Tyres

<b>235/45/18/98 V</b>					
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm	
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm	
Tyre profile depth FL					<b>5.0</b>
Tyre profile depth FR					<b>5.0</b>
Tyre profile depth RL					<b>5.0</b>
Tyre profile depth RR					<b>5.0</b>
Tyre size FL					<b>235/45 R 18 98 V</b>
Tyre size FR					<b>235/45 R 18 98 V</b>
Tyre size RL					<b>235/45 R 18 98 V</b>
Tyre size RR					<b>235/45 R 18 98 V</b>
Tyre type FL					<b>Winter</b>
Tyre type FR					<b>Winter</b>
Tyre type RL					<b>Winter</b>
Tyre type RR					<b>Winter</b>
Tyre make FL					<b>259</b>
Tyre make FR					<b>259</b>
Tyre make RL					<b>259</b>
Tyre make RR					<b>259</b>


## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		



Instrument panel, complete, Repaired, Acceptable




Bonnet, Repaired, Acceptable



Door FL, Dent(s), Acceptable



Door RL, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Acceptable




Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Acceptable



Door FR, Repaired, Acceptable



Wing FR, Repaired, Acceptable



Bodywork, No damage, Acceptable

