



VOLVO V60: 1XKN847

Vinnumber:	YV1ZW72V1L2376962	Versionname:	V60 D3 Momentum Pro 110kW/150pk 5D/P Man-6
First Registrationdate:	27/01/2020	Fiscalpower:	
Expertise Mileage:	106487	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	B601
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Dirty		

Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Airco functioning	Yes	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Transmission	OK
Exhaust gass	OK		

Degree of wear

225/50/17/98 V				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/50 R 17 98 V
Tyre size FR				225/50 R 17 98 V
Tyre size RL				225/55 R 17 98 V
Tyre size RR				225/50 R 17 98 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit

Yes Compressor

Yes

Number of charging cables (normal)

0

Number of charging cables (rapid charge)

0

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bumper grille, Scratch(es), Acceptable



Headlight L, Scratch(es), Replace



Alloy rim FL polished, Scratch(es), Acceptable



Rear light L, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable




Alloy rim RR polished, Scratch(es), Acceptable



Wing RR, Dent(s), Spot repair



Door RR, Dent(s), Paintless dent repair



Alloy rim FR polished, Scratch(es), Acceptable



Wing FR, Dent(s), Acceptable



Door FR, Dent(s) and scratch(es), Acceptable

