



SKODA Kamiq: 2CDG949			
Vinnumber:	TMBGR6NWXN3105431	Versionname:	Kamiq 1.0 TSI Clever 81kW/110pk 5D/P Man-6
First Registrationdate:	13/06/2022	Fiscalpower:	
Expertise Mileage:	72222	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c413
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options	
Number of keys total	2
Number keys remote	2
Windows electric F	Radio
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Alarm	
Navigation with screen	
Airco electronic	
Rims alloy	

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres			
205/55/17/91 V			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Continental: 4 mm	Re.R.
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			205/55 R 17 91 V
Tyre size FR			205/55 R 17 91 V
Tyre size RL			205/55 R 17 91 V
Tyre size RR			205/55 R 17 91 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		

Instrument panel, complete, Repaired, Acceptable




Roof liner, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable




Bonnet, Repaired, Acceptable



Door FL, Dent(s), Paintless dent repair




Roof pillar L, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Polish




Bumper R, Scratch(es), Polish



Alloy rim FR, Deformed / Strained, Replace



Door RR, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

