



OPEL Grandland: 2CET702

Vinnnumber:	W0VZ4DGZ0N6816787	Versionname:	Grandland 1.6 Turbo S/S Hybrid Business Edition (PHEV) 165kW/224pk 5D/P Auto-8
First Registrationdate:	27/06/2022	Fiscalpower:	
Expertise Mileage:	23040	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	outlet45
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio	
Number keys remote:	2	Front parking sensors	
GPS storage:	HD	Rear parking sensors	
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

Winter tyres:	225/55/18/102 V			
	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm
Tyre profile depth FL				5
Tyre profile depth FR				5
Tyre profile depth RL				5
Tyre profile depth RR				5
Tyre size FL				225/55 R 18 102
Tyre size FR				225/55 R 18 102
Tyre size RL				225/55 R 18 102
Tyre size RR				225/55 R 18 102
Tyre type FL				Wint
Tyre type FR				Wint
Tyre type RL				Wint
Tyre type RR				Wint
Tyre make FL				26
Tyre make FR				26
Tyre make RL				26
Tyre make RR				26

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Instrument panel, complete, Not functioning (well), Acceptable



Headlight R, Deformed / Strained, Replace



Wing trim RL, Scratch(es), Polish




Door RL, Scratch(es), Polish




Wing FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Outside rear-view mirror base L, Scratch(es), Acceptable



Bumper R, Scratch(es), Spot repair



Tailgate / Boot, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Bodywork, No damage, Check

