



SKODA Octavia Combi: 2BLZ121

Vinnnumber:	TMBJP7NX2MY135857	Versionname:	Octavia Combi 1.0 TSI Clever 81kW/110pk 5D/P Man-6
First Registrationdate:	10/01/2022	Fiscalpower:	
Expertise Mileage:	81377	Power Kw:	81
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	pp99
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
GPS storage:		Rear parking sensors:	
GPS storage:	HD	Fog lights (front):	
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

205/55/17/95 V				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 17 95 V
Tyre size FR				205/55 R 17 95 V
Tyre size RL				205/55 R 17 95 V
Tyre size RR				205/55 R 17 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

0
0

Instrument panel, complete, Repaired, Acceptable



Interior, Stain, Cleaning



Bonnet, Scratch(es), Acceptable




Alloy rim FL, Scratch(es), Acceptable



Wing RL, Dent(s), Spot repair



Door RL, Dent(s) and scratch(es), Spot repair



Wing FL, Dent(s), Acceptable



Step L, Dent(s) and scratch(es), Spot repair



Boot lid covering R, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Rear spoiler, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Spot repair



Tailgate / Boot, Scratch(es), Polish



Wing RR, Bad repair, Repair and paint (complete)



Door RR, Scratch(es), Polish



Door FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Fuel cap cover, Deformed / Strained, Replace

