



SKODA Octavia Combi: 2BQH953

Vinnumber:	TMBJJ7NX3NY069208	Versionname:	Octavia Combi 2.0 CRTDI DSG7 Clever+
First Registrationdate:	14/02/2022	Fiscalpower:	110kW/150pk 5D/P Auto-7
Expertise Mileage:	209566	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c329
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	3	Radio	
Number keys remote	3	Front parking sensors	
GPS storage		Rear parking sensors	
GPS storage	HD	Fog lights (front)	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	NOT OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/55/17/91 V				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 17 91 V
Tyre size FR				205/55 R 17 91 V
Tyre size RL				205/55 R 17 91 V
Tyre size RR				205/55 R 17 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		

Instrument panel, complete, Repaired, Acceptable



Ignition key, Not functioning (well), Acceptable




Backrest cover FL, Worn, Acceptable




Door panel RR, Scratch(es), Acceptable




Bonnet, Scratch(es), Acceptable



Bumper F, Repaired, Acceptable



Windscreen, Stone chip(s), Acceptable




Alloy rim FL polished, Scratch(es), Acceptable




Door FL, Increased paint layer, No repair



Door RL, Scratch(es), Acceptable



Wing RL, Dent(s), Spot repair



Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Boot lid covering R, Scratch(es), Acceptable



Rear window, Scratch(es), Polish



Rear spoiler, Scratch(es), Polish



Bumper R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Smart repair



Door FR, Increased paint layer, No repair



Wing RR, Dent(s), Paintless dent repair



Bodywork, No damage, Acceptable



Bodywork, Inspection +, Photo complémentaire



Roof, Scratch(es), Acceptable

