



**MERCEDES EQS: 2CDY010**

|                                   |                          |                        |                                                          |
|-----------------------------------|--------------------------|------------------------|----------------------------------------------------------|
| Vinnumber:                        | <b>W1K2971211A016827</b> | Versionname:           | <b>EQS EQS 350 Business Line 215kW/292pk 5D/P Auto-1</b> |
| First Registrationdate:           | <b>17/06/2022</b>        | Fiscalpower:           |                                                          |
| Expertise Mileage:                | <b>107409</b>            | Power Kw:              |                                                          |
| Bodytype:                         |                          | Body colour            | <b>Dark Grey</b>                                         |
| Gearbox:                          | <b>Automatic</b>         | Type of rims (mounted) | <b>Aluminium</b>                                         |
| Transmission:                     | <b>Back</b>              | Parking lot            | <b>c418</b>                                              |
| Fueltype:                         | <b>Electric</b>          |                        |                                                          |
| Number of doors                   | <b>5</b>                 |                        |                                                          |
| Number of seats                   | <b>5</b>                 |                        |                                                          |
| Number head rests                 | <b>5</b>                 |                        |                                                          |
| Type of rims (mounted)            | <b>Aluminium</b>         |                        |                                                          |
| Certificate of Conformity         | <b>Yes</b>               |                        |                                                          |
| Category                          | <b>Passenger Car</b>     |                        |                                                          |
| Registration Certificate Car (BE) | <b>Yes</b>               |                        |                                                          |
| Bodywork                          | <b>Clean</b>             |                        |                                                          |
| Interior                          | <b>Clean</b>             |                        |                                                          |

**Options**

|                                |          |                       |  |
|--------------------------------|----------|-----------------------|--|
| Number of keys total           | <b>2</b> | Radio                 |  |
| Number keys remote             | <b>2</b> | Lining leather        |  |
| Windows electric F             |          | Sun Roof electric     |  |
| Windows electric R             |          | Front parking sensors |  |
| Cruise Control                 |          | Rear parking sensors  |  |
| Steering wheel multifunctional |          |                       |  |
| Seats F heated                 |          |                       |  |
| Alarm                          |          |                       |  |
| Navigation with screen         |          |                       |  |
| Airco electronic               |          |                       |  |
| Rims alloy                     |          |                       |  |

**Limited Technical Inspection**

|                     |           |              |           |
|---------------------|-----------|--------------|-----------|
| Idle position       | <b>OK</b> | Sound engine | <b>OK</b> |
| Engine startingtime | <b>OK</b> | Clutch test  | <b>OK</b> |
| Exhaust gass        | <b>OK</b> | Transmission | <b>OK</b> |

**Tyres**

| Location | Position | Measures                            | Depth  | Make        | Type   |
|----------|----------|-------------------------------------|--------|-------------|--------|
| Front    | Left     | 235 / 55 / 19 / 101 / V / Aluminium | 6,0 mm | Bridgestone | Summer |
|          | Right    | 235 / 55 / 19 / 101 / V / Aluminium | 6,0 mm | Bridgestone | Summer |
| Rear     | Left     | 235 / 55 / 19 / 101 / V / Aluminium | 6,0 mm | Bridgestone | Summer |
|          | Right    | 235 / 55 / 19 / 101 / V / Aluminium | 6,0 mm | Bridgestone | Summer |






**Assistance equipment**


|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>1</b>   |            |            |
| Number of charging cables (rapid charge) | <b>1</b>   |            |            |

**Seat cover FL, Worn, Check**




**Instrument panel, complete, Repaired, Acceptable**






Boot lid covering R, Broken, Smart repair




Bumper R, Scratch(es), Acceptable




Rear light L, Scratch(es), Polish




Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable




Door RR, Dent(s), Paintless dent repair



Door FR, Scratch(es), Acceptable



Outer door handle FR, Scratch(es), Acceptable



Sill trim R, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Panoramic roof, Scratch(es), Polish

