



MERCEDES CLA Shooting Brake: 1YHX328

Vinnnumber:	W1K1186031N157153	Versionname:	CLA Shooting Brake CLA 180 d Business Solution
First Registratiedate:	7/09/2020	Fiscalpower:	85kW/116pk 5D/P Man-6
Expertise Mileage:	37223	Power Kw:	
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c319
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear

205/60/16/92 V				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 92 V
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

number of charging cables (normal)
Number of charging cables (rapid charge)

0
0


Instrument panel, complete, Not functioning (well), Check



Bumper F, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Interior covering C pillar R, Scratch(es), Acceptable



Bumper R, Scratch(es), Polish



Rear light L, Scratch(es), Polish




Outside rear-view mirror base R, Scratch(es), Acceptable



Roof pillar R, Dent(s), Paintless dent repair





Door FR, Scratch(es), Polish



Door RR, Scratch(es), Polish



Bodywork, Not original part, Remove lettering



Roof, Chemical polution, Polish

