



**MERCEDES GLA: 2CCE044**

Vinnnumber:	<b>W1N2477101J406907</b>	Versionname:	<b>GLA GLA 180 d Business Solution Essential</b>
First Registrationdate:	<b>31/05/2022</b>	Fiscalpower:	<b>85kW/116pk 5D/P Auto-8</b>
Expertise Mileage:	<b>109721</b>	Power Kw:	
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Back</b>	Parking lot:	<b>a217</b>
Fueltype:	<b>Diesel</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total	<b>2</b>	Radio	
Number keys remote	<b>2</b>	Front parking sensors	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

**Limited Technical Inspection**

Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Transmission	<b>OK</b>

**Tyres**

<b>215/65/17/99 H</b>				
Winter tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>215/65 R 17 99 H</b>
Tyre size FR				<b>215/65 R 17 99 H</b>
Tyre size RL				<b>215/65 R 17 99 H</b>
Tyre size RR				<b>215/65 R 17 99 H</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>256</b>
Tyre make FR				<b>256</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Number of charging cables (normal)  
Number of charging cables (rapid charge)

0  
0

Instrument panel, complete, Repaired, Acceptable



Seat cover RL, Stain, Cleaning



Seat cover FR, Stain, Cleaning



Backrest cover FR, Stain, Cleaning



Bumper moulding F, Scratch(es), Replace



Bumper F, Scratch(es), Polish



Bumper spoiler F, Scratch(es), Acceptable



Shutter / cover F, Not original part, Acceptable



Headlight L, Scratch(es), Replace



Headlight R, Scratch(es), Replace



Wing RL, Dent(s), Spot repair



Central pillar L, Dent(s), Spot repair



Door RL, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Spot repair



Wing trim RL, Deformed / Strained, Replace



Roof pillar L, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Rear light L, Scratch(es), Replace



Rear light R, Scratch(es), Replace



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Spot repair



Central pillar R, Dent(s), Spot repair



Wing trim RR, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Roof pillar R, Dent(s), Paintless dent repair



Bodywork, No damage, Acceptable

