



PEUGEOT 308: 2CHE577

Vinnumber:	VR3FPHNPLNY554514	Versionname:	308 1.2 PureTech 110 S/S Active Pack 81kW/110pk
First Registrationdate:	27/07/2022	Fiscalpower:	5D/P Man-6 - CO2 onvoldedig
Expertise Mileage:	99338	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:	Front	Parking lot	d245
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 16 / 91 / H / Steel	4,0 mm	Michelin	Summer
	Right	205 / 55 / 16 / 91 / H / Steel	4,0 mm	Michelin	Summer
Rear	Left	205 / 55 / 16 / 91 / H / Steel	6,0 mm	Goodyear	Summer
	Right	205 / 55 / 16 / 91 / H / Steel	6,0 mm	Goodyear	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Door panel FL, Burned, Smart repair



Floor covering FL, Burned, Smart repair



Seat cover FL, Stain, Acceptable



Seat cover FR, Burned, Smart repair



Roof liner, Burned, Smart repair




Instrument panel, complete, Repaired, Acceptable




Bumper F, Scratch(es), Spot repair



Bonnet, Chemical pollution, Polish



Roof pillar L, Dent(s), Paintless dent repair



Door FL, Dent(s) and scratch(es), Spot repair



Outside rear-view mirror housing L, Scratch(es), Polish




Bumper R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Wheel cover RR, Scratch(es), Replace




Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover FR, Scratch(es), Acceptable



Roof pillar R, Dent(s), Paintless dent repair



Step R, Dent(s) and scratch(es), Spot repair



Roof, Dent(s), Acceptable



Bodywork, No damage, Acceptable

