


SKODA Superb Combi: 2DVA711

Vinnnummer:	TMBJN7NP4P7046467	Versionname:	Superb Combi 1.5 TSI ACT DSG7 Clever
First Registrationdate:	3/07/2023		110kW/150pk 5D/P Auto-7 (4 seizoenen Banden) - CO2 onvolledig
Expertise Mileage:	82135	Fiscalpower:	
Bodytype:		Power Kw:	
Gearbox:	Automatic	Body colour:	Black
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	b413
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

215/55/17/98 W				
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Barum: 4 mm	Re.R.	Barum: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/55 R 17 98 W
Tyre size FR				215/55 R 17 98 W
Tyre size RL				215/55 R 17 98 W
Tyre size RR				215/55 R 17 98 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				258
Tyre make FR				258
Tyre make RL				2478
Tyre make RR				2478

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		

Instrument panel, complete, Repaired, Acceptable




Engine insulation, Damaged, Replace



Bumper F, Scratch(es), Acceptable




Bonnet, Scratch(es), Polish



Door FL, Scratch(es), Acceptable



Door RL, Dent(s), Paintless dent repair



Wing RL, Scratch(es), Polish




Bumper R, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Wing RR, Scratch(es), Polish



Bodywork, No damage, Acceptable

